



COLONIAL BANK | Lady Lake, Florida

8,020 Square Foot Bank/Medical

New Bank Branch office BUILDING FEATURES INCLUDE:

- Butler Steel Trusses “Skyline System”
- Butler VSR standing seam roof
- Brick veneer over masonry block wall system
- Banking features include security entry system, vault and drive thru ATM